

# Checking the USB Connection

Begin with a Right Click on My Computer



Then Left click on Properties



This System Properties screen will appear. Left click on the Hardware Tab.




# Checking the USB Connection

In the middle of the screen, left click on “Device Manager.”



This is the lower portion of the e screen that appears.



At the bottom of the window you will see the symbol and words, “**Universal Serial bus Controllers.**”

Click the “+” sign in front of the symbol (as has been done above) to see what Serial devices are connected to the system. Note the “**DryFire simulator**” is connected.

# Checking the USB Connection

Now, double click on “DryFire simulator.”

This screen will appear.



It says, “This device is working properly.”

Now, click on the “Driver” tab to show this picture.



It shows the proper driver is installed (FTDI).